10.14.11

Friday

Saturday

Sunday

Monday

TENNESSEE DEPARTMENT OF TRANSPORTATION EROSION PREVENTION/SEDIMENT CONTROL INSPECTION REPORT

TDOT EPSC INSPECTION FORM Rev. Feb 2010

Reason For Inspection:

1st Weekly

2nd Weekly

											DATE: / O.	7.11	
State Route	(SR) / US Rou	te or Road Na	me and De	scription:			Are correcti	ve actions r	equired by	this inspec	tion report (Y/N):		-
		Wolfi	River Blvd.					13		YES			
County(ies):		TDOT PIN:		NPDES Per	mit (NOC)	#:	Number of i	Vew	Number of F	Recurring	Number of New	Number of Un-Corre	ecled
Sh	relby	1016	15	Т	NR153299		Corrective A	Actions:	Corrective A	Actions:	Sediment Releases:	Sediment Releases	:
TDOT Const	Iruction No.:	TDOT Contra	ct No.:	Contractor:			(6)		1				
7994-	1535-54			Acuff	Enterprises	s Inc.							
prepared und designed to a information promation. I formation. I of erosion and above. I certified outfrecorded in II	er penalty of law the my direction of sessure that qualifures enter the ente	or supervision in ied personnel part on my inquiry persons directly clions of storm rols have been and sediment comed as planned a am aware that	n accordance properly gath of the person y responsible water dische performed as portrols in the and designed there are signed	e with a syste ered and eva n or persons e for gatherin arge points (c s recorded in drainage are I in working o gnificant pena	m Iluated who g the outfalls), and the table ea of the order as allies for	Contractor	EPSC Inspe C Project Ma pe):	d "Jerry" St ector and Ti Tom Acuff	anfill itle (print or		Signature: Signature: Signature:	Stanfil Roseff	
		TDOT EPSC	: Inspectio	n Weekly R	lainfall Dat	a Log							
		Predicted	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall	Rainfall			ntractor Agrees with Ir	spection Report:	
Date	Day of Week		~	Gauge 2	Gauge 3	Gauge 4	Gauge 5	Gauge 6	Duration	NO	or (YES)		
1-1/11	Conde	(%)	(in)	(in)	(in)	(in)	(in)	(in)	(hr)	ii No, expi	ain and initial:	- 1	-
10.16.11	Sunday	0			N/A	N/A	N/A	N/A		· 4 Cc	rections a	re sking ma	ar.
10.17.11	Monday	10	0	0	N/A	N/A	N/A	N/A				<i></i>	
10.18.11	Tuesday	80			N/A	N/A	N/A	N/A					
10.19.11	Wednesday	0			N/A	N/A	N/A	N/A					
10.20.11	Thursday	0			N/A	N/A	N/A	N/A					

Predicted Precipitation Source:

0

0

www.weather.com

N/A

Page 1 of 8

(Additional pages may be attached, if needed)

	٠.			
	1)	٠.		
BL.	10	~	Ċ	
Э.	ال	۲,	۱,	
UR	E	1:	41	
	- 1	1	21	
Z	1	⋛	/:	
12	110	.77		

State/US Route or Road Name:

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

CONDITION CODES

Date	10/17/2011	

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
1	1	14+14	LT	10/17/2011		22,35	FM	Weekly cleaning will be required, until further notice.
1A	1	21+50	RT	10/17/2011		41	FM	Backfilling RCBC in progress.
1B	1	22+00	RT	10/17/2011		41	FM	Backfilling RCBC in progress.
1C	1	21+00	LT	10/6/2011	T = 10-6-11	10,12,15,35,41	FM	Monitoring BMP's in place.
2A	1	33+50	LT,CL	10/17/2011		15,16,24	FM	Additional BMP's needed. See Photo
2B	1	35+50	LT	10/17/2011		16,24	FM	Weekly cleaning for stream crossing required, until further notice. BMP's needed. See Photo
3	1	34+50	LT					The area has not been disturbed.
4	1	40+00	RT	10/17/2011		15,16,33,43	I,RO	Temp. stabilization protection for proposed realigned channel incomplete, temp. hydroseed in place, 85% of rip-rap in place. Re-Hydro seed disturbed area. Stabilize slope. See Photos
5A	1	49+00	RT	10/13/2011		16	FM	Monitoring BMP's in place.
5B	1	50+00	RT	10/13/2011		9,16	FM	Monitoring BMP's in place.

EROSION AND SEDIMENT CONTROL MEASURE CODES

Temporary Silt Fence / Filter Barrier Temporary seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance Temporary Diversion Berm or Ditch 16 Temporary Mulch Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner Rock Silt Screen Future Maintenance Brush Barrier 5 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing C Cleaning Needed Sediment Removal 6 20 Riprap Outlet Structure **Enhanced Silt Fence** Increase Measures 7 Straw Bale Check Riprap Energy / Velocity Dissipater 21 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) Final Stabilized Polyethylene Sheeting 25 11 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Other (O31): Temporary Stream Diversion 40 Sheet Pilling 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Haul Road 41 Other (O#2): 14 Permanent Seeding with Mulch or Sod Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

Stream Realignment

State/US	Route or	Road	Name

Ma	IF	River	Dlyd
/VO	п	River	BIVO.

TDOT Construction No.: 79954-3537-54

799	EA	25	27	E
799	74	1.7	. 7/	7

TDOT	Contract No.:	

CONDITION CODES

Date	10/17/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
								Weekly cleaning for stream crossing
5C	1	44+00	LT	10/17/2011		16,24	FM	required. BMP's needed @ New Channel Realignment. See Photo
6	1	56+00	LT	10/13/2011		16, 32	FM	Re-draining pond in progress. No activity during insprction.
7	1	60+00	RT	10/17/2011		16	FM	Actively clearing and mulching.
8A	1	73+00	RT	10/17/2011		16,24,42	FM	Weekly cleaning for stream crossing will be required, until further notice.
8B	2	75+50	RT	9/29/2011		16,24,35,41	S	Currently Stable, Monitoring BMP's.
8C	1	71+00	LT	10/17/2011		16,42	FM	Construction floatables removed from flowline.
8D	2	75+50	LT	10/3/2011	T = 10-3-11	16,35,42	FM	Monitoring BMP's. Weekly watering required until seed germinates.
8E	1	71+50	LT					The area has not been disturbed.
9A	2	80+00	RT	9/29//11	T = 10-3-11	6,15,33,35	FM	Weekly watering required until seed germinates.
9B	2	80+00	LT	9/29//11	T = 10-3-11	15,16,17,,35	FM	Weekly watering required until seed germinates.

EROSION AND SEDIMENT CONTROL MEASURE CODES

M Maintenance Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch 29 Excess Dirt Removed from Rdwy. Daily Upgrade Needed (Failure Noted) 2 Temporary Diversion Berm or Ditch Temporary Mulch 30 Haul Roads Dampened for Dust Control 3 Temporary Slope Drain 17 Erosion Control Blanket 31 Ditch Liner Replacement Needed Rock Silt Screen FM Future Maintenance 4 Rock Check Dams 18 Flexible Channel Liner 32 C Brush Barrier 19 Catch Basin / Storm Inlet Protection 33 Temporary Silt Fence with Backing Cleaning Needed 6 Sediment Removal 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 21 Riprap Energy / Velocity Dissipater 35 Sediment Tube W Too Wet to Work Conditions 8 Sand Bags 22 Curb, Gutter, or Storm Sewer Protection 36 Sediment Dam RO Repeat Occurrence Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues SR Sediment Release 9 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 10 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) Polyethylene Sheeting 11 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 12 27 Haul Road Other (O#2): Geotextile Preserve Natural Resource / Buffer Zone 41 13 Permanent Seeding with Mulch or Sod 42 **Bridge Construction** Other (O#3): 28 Mineral Aggregate Base on Subgrade

EPSC Inspection

Page 3 of 8

State/US	Route	or	Road	Name
Clate, CO	riouto	O1	rtoau	TTOITIC.

Wolf River Blvd.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:

Date	10/17/2011
Date	10/17/2011

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
9C	2	79+50	LT	9/29/2011	T = 10-03-11	15,16,20,33	FM	Weekly watering required until seed germinates.
10A	2	85+00	RT	9/29/2011		15,16,35,41	FM	Currently active construction site. Sand bag upstream, remove daily during construction.
10B	2	85+00	RT	9/29/2011		15,16,35,41	FM	No work done in this area on inspection date.
10C	2	85+50	LT	9/29/2011		10,15,16,35,41	FM	No work done in this area on inspection date.
10D	2	84+50	LT	9/29/2011		10,15,16,35,41	FM	No work done in this area on inspection date.
11A	2	92+50	RT	10/17/2011		35,41	FM	Floatables removed. Construction activity during inspection.
11B	2	92+50	LT	10/6/2011		10,32,35,41	FM	Remove floatables. See photo
11C	2	92+00	LT	10/6/2011		10,32,35,41	FM	Remove floatables. See photo
	1	11+28	LT	10/17/2011		19,35	FM	Daily cleaning is required, until further notice.
	1	13+40	RT	10/17/2011		23,29,30	FM	Daily cleaning will be required, until further notice.
ä	1	107+75	CL N AND SEDIME	10/17/2011	IEASURE CODES	23,29,30	FM	Daily cleaning will be required, until further notice.

EROSION AND SEDIMENT CONTROL MEASURE CODES Temporary Silt Fence / Filter Barrier 15 Temporary Seeding with Mulch

27

2 Temporary Diversion Berm or Ditch

Temporary Slope Drain 3

Rock Check Dams 4

5 Brush Barrier

6 Sediment Removal 7

Straw Bale Check

Sand Bags 8

9 Sediment Trap / Basin

10 Temp Sediment Filter Bag / Dewatering

Polyethylene Sheeting 11

12 Machined Rip Rap

13 Geotextile

14 Permanent Seeding with Mulch or Sod 16 Temporary Mulch

17 **Erosion Control Blanket**

18 Flexible Channel Liner

Catch Basin / Storm Inlet Protection 19

20 Riprap Outlet Structure

21

Riprap Energy / Velocity Dissipater 22

Curb, Gutter, or Storm Sewer Protection 23 Temporary at Construction Exit / Entrance

24 Temporary Stream Crossing

25 Turbidity Barrier / Silt Boom

26 Temporary Stream Diversion

28 Mineral Aggregate Base on Subgrade

Preserve Natural Resource / Buffer Zone

Excess Dirt Removed from Rdwy, Daily 30 Haul Roads Dampened for Dust Control

31 Ditch Liner

32 Rock Silt Screen 33

Temporary Silt Fence with Backing 34 Enhanced Silt Fence

35 Sediment Tube 36 Sediment Dam

37 Concrete Washout, other pollution Issues

38 Berm (soil, riprap, rock)

39 Gabion

40 Sheet Pilling 41 Haul Road

Bridge Construction

CONDITION CODES

Maintenance

M

U Upgrade Needed (Failure Noted)

R Replacement Needed

FM Future Maintenance

C Cleaning Needed 1 Increase Measures

W Too Wet to Work Conditions

RO Repeat Occurrence SR Sediment Release

FS Final Stabilized

S Stable (No Action Needed) Other (024):

Onlei (031)	
Other (O#2):	
Other (O#3):	

State/US	Route or	Road	Name

٨		1.				
١V	U	п	К	iver	D	ıva.

TDOT Construction No.:

79954-3537-54

TDOT Contract No.:	
--------------------	--

CONDITION CODES

Date _____10/17/2011

Outfall Name or Station No. *(Existing Structure)	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
* 109+51	2	East side of WRB	RT	10/17/2011		19,22	FM	Daily cleaning will be required, until further notice and Clean H.C. Ramp.
* 109+11	2	South side of Farmington	RT	10/17/2011		19,22	FM	Daily cleaning will be required, until further notice and Repair inlet protection.
* 12+80	1	North side of WRB	LT	10/17/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	Walking Trail 36+00	LT	7/20/2011	T = 7-20-11	5,35	s	Currently stable, Monitoring BMP's
	1	Sta. 29+50 Slope	LT	7/20/2011	T= 9-01-11	16	S	Currently stable.
		Sta. 13+40 - Sta. 107+75	LT, RT or CL	10/13/2011		30	FM	Haul roads dampened frequently for dust control, until further notice.
	2	76+50 - 103+46	RT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed germinates.
	2	92+50 - 107+00	LT	9/29/2011	T = 10-03-11	15,16,35	FM	Weekly watering required until seed germinates.
	1	6+75	LT	10/17/2011	**	19,22	FM	Daily cleaning will be required, until further notice.
	1	25+00	RT	9/29/2011	T = 10-03-11	15,33,35,41	FM	Monitoring BMP's. Weekly watering required until seed germinates.
	1	27+00	RT	10/3/2011	T= 10-03-11	15,16	S	Currently stable, Monitoring BMP's
	11	34+00	RT	8/25/2011	T= 8-25-11	16	S	Currently stable, Monitoring BMP's

EROSION AND SEDIMENT CONTROL MEASURE CODES

1 Temporary Silt Fence / Filter Barrier Temporary Seeding with Mulch Excess Dirt Removed from Rdwy. Daily Maintenance 2 Temporary Diversion Berm or Ditch Temporary Mulch 30 Haul Roads Dampened for Dust Control Upgrade Needed (Failure Noted) Temporary Slope Drain **Erosion Control Blanket** 3 17 31 Ditch Liner Replacement Needed Rock Check Dams 18 Flexible Channel Liner 32 Rock Silt Screen Future Maintenance 5 Brush Barrier 19 Catch Basin / Storm Inlet Protection Temporary Silt Fence with Backing Cleaning Needed Sediment Removal 6 20 Riprap Outlet Structure 34 Enhanced Silt Fence Increase Measures Straw Bale Check 7 21 Riprap Energy / Velocity Dissipater Sediment Tube W Too Wet to Work Conditions Sand Bags 8 Curb, Gutter, or Storm Sewer Protectfon 22 36 Sediment Dam RO Repeat Occurrence 9 Sediment Trap / Basin 23 Temporary at Construction Exit / Entrance 37 Concrete Washout, other pollution Issues Sediment Release 10 Temp Sediment Filter Bag / Dewatering 24 Temporary Stream Crossing 38 Berm (soil, riprap, rock) FS Final Stabilized 11 Polyethylene Sheeting 25 Turbidity Barrier / Silt Boom 39 Gabion S Stable (No Action Needed) 12 Machined Rip Rap 26 Temporary Stream Diversion 40 Sheet Pilling Other (O31): 13 Geotextile 27 Preserve Natural Resource / Buffer Zone Haul Road Other (O#2): Permanent Seeding with Mulch or Sod 14 Mineral Aggregate Base on Subgrade **Bridge Construction** Other (O#3):

EPSC Inspection



0 id Name:	Wolf River Blvd.	TDOT Construction No.:	79954-3537-54	TDOT Contract No.:

Date	10/17/2011	
------	------------	--

Outfall Name or Station No.	Rain Gage No.	Approx. Station No. From / To	LT, RT or Centerline	Date Last Disturbed	Date of Stabilization and Code T = Temp. P = Perm.	Existing EPSC Control Measure Codes*	Current Condition Codes*	Corrective Action(s) or Comments
	1	21+33 - 26+00	LT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed germinates.
	1	21+33 - 26+00	RT	10/10/2011	T = 10-6-11	15,16,35,41	FM	Weekly watering required until seed germinates.
	1	25+00	LT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	25+00	RT	9/29/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	27+50	RT	10/6/2011	T = 10-6-11	15,16,33,35,41	FM	Currently stable, monitoring BMP's.
	1	31+90	RT	9/29/2011	T = 10-6-11	15,16,35	FM	Currently stable, monitoring BMP's.
	1	15+60	RT	9/15/2011	T = 10-6-11	15,16,33,35	FM	Currently stable, monitoring BMP's. Weekly watering required until seed germinates.
* 108+37		North side of WRB	LT	10/13/2011		19,22	FM	Daily cleaning will be required, until further notice.
	1	23+00 - 26+00	RT	9/29/2011	T = 10-6-11	33,41	FM	Currently stable, monitoring BMP's.

EROSION AND SEDIMENT CONTROL MEASURE CODES

1	Temporary Silt Fence / Filter Barrier	15	Temporary Seeding with Mulch	29	Excess Dirt Removed from Rdwy, Daily	М	Maintenance
2	Temporary Diversion Berm or Ditch	16	Temporary Mulch	30	Haul Roads Dampened for Dust Control	U	Upgrade Needed (Failure Noted)
3	Temporary Slope Drain	17	Erosion Control Blanket	31	Ditch Liner	R	Replacement Needed
4	Rock Check Dams	18	Flexible Channel Liner	32	Rock Silt Screen	FM	Future Maintenance
5	Brush Barrier	19	Catch Basin / Storm Inlet Protection	33	Temporary Silt Fence with Backing	С	Cleaning Needed
6	Sediment Removal	20	Riprap Outlet Structure	34	Enhanced Silt Fence	Ĩ	Increase Measures
7	Straw Bale Check	21	Riprap Energy / Velocity Dissipater	35	Sediment Tube	w	Too Wet to Work Conditions
8	Sand Bags	22	Curb, Gutter, or Storm Sewer Protection	36	Sediment Dam	RO	Repeat Occurrence
9	Sediment Trap / Basin	23	Temporary at Construction Exit / Entrance	37	Concrete Washout, other pollution Issues	SR	Sediment Release
10	Temp Sediment Filter Bag / Dewatering	24	Temporary Stream Crossing	38	Berm (soil, riprap, rock)	FS	Final Stabilized
11	Polyethylene Sheeting	25	Turbidity Barrier / Silt Boom	39	Gabion	S	Stable (No Action Needed)
12	Machined Rip Rap	26	Temporary Stream Diversion	40	Sheet Pilling	Other (O31):	18 1800 18 18 18 18 18 18 18 18 18 18 18 18 18
13	Geotextile	27	Preserve Natural Resource / Buffer Zone	41	Haul Road	Other (O#2):	
14	Permanent Seeding with Mulch or Sod	28	Mineral Aggregate Base on Sub grade	42	Bridge Construction	Other (O#3):	

CONDITION CODES




Outfall 2A Sta. 33+50 LT,CL Additional BMP's Needed. (FM)



Outfall 2B Sta. 35+50 BMP's Needed (FM)




Outfall 4 Sta. 40+00 RT Re-Hydro Seed disturbed area and Stabilize Slope. (J,RO)



Outfall 4 Sta. 40+00 RT Stabilize Slope. (I,RO)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138



Outfall 5C Sta, 44+00 LT.
BMP's Needed (FM)

Outfall 11B Sta. 92+50 LT. & Outfall 11C 92+00 LT. Remove Floatables from flow line. (FM)



City of Germantown 1920 S. Germantown Road Germantown, TN 38138